Killy Langford Brices Mill Road 18th Century

Killy Langford is located on the east branch of Langford Creek. Interestingly, the farm possesses a combination of structures dating from three different periods. The squared log or plank 1-1/2 story section may be the earliest. Its one room and loft structure had a fireplace on its east gable and an enclosed stair in the northeast corner. The adjoining 1-1/2 story frame section, built slightly taller, was probably constructed in the late 18th or early 19th Century. It appears to have been another one room and loft structure with its stair in the southeast corner adjacent the fireplace. Both of these sections were built facing south.

١.

A third section, built in the 1880's, is set at right angles to the others and has its facade looking west down the lane and across the open expanse of fields. The final wing may have been built by William Ford, who appears as owner in the 1877 Atlas. It originally had a front porch across the facade and a one story bay window on the south gable. Overall, the builder of the final section brought the farmhouse into an equal footing with most of Kent County's farmhouses of the period.

Form 10-445 (5/62)

1. STATE Md

COUNTY Ment

TOWN Chestertown VICINITY

STREET NO.

ORIGINAL OWNER Continue

ORIGINAL USE dwelling

PRESENT OWNER Harry

PRESENT USE dwelling

WALL CONSTRUCTION leg + frame

NO. OF STORIES 12

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY K-81

2. NAME Killy Longfords

DATE OR PERIOD possibly branchurn STYLE Log cabin of frame ARCHITECT BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC IND

Killy Langfords is a house composed of three sections. He works from a section of a late 19th century form house; the most better and the section, a late 18th century from 12 story, 2 boay lone structure, with a flat domor on each side the final section is a simple lag structure while many date from the 19th century. It also has an domor on each side of the "A" roop. The interior he heen revoluted and a doubte window we cut for the section of log still remain contricts. Here is investing of while because the log construction.

5. PHYSICAL CONDITION OF STRUCTURE Endangered NO Interior Good Exterior Good

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER
Michael Bowne

DATE OF RECORD Oct 2, 1968

Eilly Longfords is a house composed of three sections. The westernmost section is a later 19th-century farmhouse; the middle section, set to the rear of the large house, a late eighteenth-century frame one-and-one-half story, two bay long structure, with a flat headed dormer on each side. The final section is a simple log structure which may date from the seventeenth century. It also has one dormer on each side of the A roof.

The interior has been remodeled and a double window was cut from the center wall, the sections of log still remain outside. This is worthy of note because of the log construction.

